



Campbell Scientific Inc
 815 West 1800 North • Logan, Utah 84321-1784
 Phone 435.227.9105 • Fax 435.227.9106

PO Number	CC/RMA 24692
Receipt Number	24692-1
Receipt Date	07-18-16
AE	Jeff Adams
Customer Number	42282
Page	1

Received 8/24/2016

RMA Customer Report

B I L L T O	Joseph Verfaillie University Of California Berkeley Enviro Science Policy & Mgmt 130 Mulford Hall Berkoley, CA 94720-3110
--	---

S H I P T O	Elke Eichelmann University of California Berkeley ESPM-ES Dept 54 Mulford Hall MC3114 Berkeley, CA 94720
--	--

Contact	Elke Eichelmann	Freight Terms	PP&A
Phone	415-412-2410	Ship Via	UPS GROUND
Fax		Payment Terms	Visa Credit Card
Email	eeichelm@berkeley.edu		

The below Customer Item(s) are being returned after repair

Li.No	Part.No/Description	Qty	Serial.No	Problem	Corrective Action
1	28790 CS451 STAINLESS STEEL SDI-12 / RS-232 PRESSURE W/20' LC & DESI TUBE	1	20010770	Voltage output low. Estimate.	Tested unit and ran through the environmental calibration chamber. Unit meets specs.

Name	Code	Rate	Hours	Chargeable
Scott Wright	C	125.0000	1.00	

Part.Number	Description	Code	Price	Qty	Chargeable
25425	CS450, CS451, CS455, or CS456 Recalibration w/Documentation	Y	80.0000	1.00	80.00
TOTAL:					\$80.00

Li.No	Part.No/Description	Qty	Serial.No	Problem	Corrective Action
2	21880 CS450-L STAINLESS STEEL SDI-12 / RS-232 PRESSURE W/20' LC & DESI TUBE	1	20010046	Output variation when exposed to air. Estimate.	Tested unit, it has calcium on the element and needs cleaned. Cleaned and ran through the environmental calibration chamber. Unit meets specs.

Name	Code	Rate	Hours	Chargeable
Scott Wright	C	125.0000	1.00	
Scott Wright	Y	125.0000	0.50	62.50

Part.Number	Description	Code	Price	Qty	Chargeable
25425	CS450, CS451, CS455, or CS456 Recalibration w/Documentation	Y	80.0000	1.00	80.00
TOTAL:					\$142.50

Li.No	Part.No/Description	Qty	Serial.No	Problem	Corrective Action
3	20657 CS106 CS106 VAISALA PTR110	1	H0160069	Readings low. Estimate.	Tested against reference. Inspected inside of sensor, no problems found. Successfully

Continued



**CAMPBELL
SCIENTIFIC**
WITH MEASUREMENTS MATTER

Campbell Scientific Inc
815 West 1800 North • Logan, Utah 84321-1784
Phone 435.227.9105 • Fax 435.227.9106

PO Number	CC/RMA 24692
Receipt Number	24692-1
Receipt Date	07-18-16
AE	Jeff Adams
Customer Number	42282
Page	2

RMA Customer Report

B I L L T O	Joseph Verfaillie University Of California Berkeley Enviro Science Policy & Mgmt 130 Mulford Hall Berkeley, CA 94720-3110
----------------------------	---

S H I P T O	Elke Eichelmann University of California Berkeley ESPM-ES Dept 54 Mulford Hall MC3114 Berkeley, CA 94720
----------------------------	--

Contact	Elke Eichelmann	Freight Terms	PP&A
Phone	415-412-2410	Ship Via	UPS GROUND
Fax		Payment Terms	Visa Credit Card
Email	eeichelm@berkeley.edu		

The below Customer Item(s) are being returned after repair

BAROMETER (500 - 1100

calibrated by Vaisala. Tested & confirmed proper function when received back.

Name.....	Code	Rate.....	Hours....	Chargeable
Brady Mikesell	C	85.0000	0.50	

Part.Number.....	Description.....	Code	Price.....	Qty.....	Chargeable
16085	Barometer Recalibration w/ Documentation	Y	230.0000	1.00	230.00
TOTAL:					\$230.00

4	16224	1	6097	Not reading correctly. Estimate.	Tested & inspected sensor. Sensor shows "NAN" readings for cond. & temp. Sensor is damaged internally. Sensor is beyond repair.
---	-------	---	------	-------------------------------------	---

Name.....	Code	Rate.....	Hours....	Chargeable
Brady Mikesell	N	85.0000	0.35	
TOTAL:				\$0.00