

LI-COR Service Report RMA 00248550 RMA Received on: 10/17/2023

## **Customer Information:**

University of California - Berkeley Berkeley, CA 94720 UNITED STATES Daphne Szutu daphneszutu@berkeley.edu

Serial #	Part	<u>Oty</u>	Line Item Subtotal
75H-2514	7500-904: CHOPPER MOTOR FACTORY (LI-7500/A, 7200)	1.00	1200.00
75H-2514	7500CAL: RECALIBRATION (LI- 7500/A/RS/DS)	1.00	960.00
S. Carlos	7300/14 (K6/D/5)	Total:	\$2,160.0

\*Total does NOT include shipping charges. They will be prepaid and added to the final invoice. All values are in US Dollars. Notes on Charges:

RMA Model & Serial Number(s)				
Model	4	Serial Number		
LI-7540 Head (75A)	75H-2514		-	

## **Service Notes**

Inspected the unit and found the chopper motor defective. Replaced the defective part, subjected the unit to environmental tests and calibrated.

Phone: 800-447-3576 Phone: 402-467-3576 envsupport@licor.com