VAISALA

1

Service Report

Date

2024-05-28

Case #

00673130

Buyer's reference

BB01852855

University of California Berkeley JosephVerfaillie

Products Serial Number

Page 1/1

GMP343 N2210009

Service(s) performed

Services for GMP343 Standard Calibration Repair Service for GMP343 Probe Carbon Dioxide Calibration for GMP343 Probe

Reason for return

Bad CO2 readings, reporting E02: IR source failure and E08: X-Signal out of scale

Problem(s) found

Device failed in calibration due to faulty sensor.

Action(s) taken

Sensor module, body of the GMP343 and filter changed. Operation tested, adjustment made and calibrated. Calibration certificate H30-24220020 issued.