

## LI-COR Service Report RMA 00249222

Phone: 800-447-3576

Phone: 402-467-3576

envsupport@licor.com

RMA Received on: 11/16/2023

## **Customer Information:**

University of California - Berkeley Berkeley, CA 94720 UNITED STATES Daphne Szutu daphneszutu@berkeley.edu

Serial #	<u>Part</u>	<u>Oty</u>	Line Item Subtotal
	: .		
AIU-1866	9672-084: CONTR 75W PWR SUP MOD V2 PCA	1.00	0.00

<sup>\*</sup>Total does NOT include shipping charges. They will be prepaid and added to the final invoice. All values are in US Dollars. Notes on Charges:

RMA Model & Serial Number(s)				
<u>Model</u>		Serial Number		
LI-7540 Head (75A)	75H-2669			
LI-7550	AIU-1866	***		

## **Service Notes**

Inspected the units and found the main power supply inoperative. Replaced the defective power supply under warranty, subjected the units to environmental tests and verified the operation of the units.